

Examples of common wood rot.



Wall cavity under a deck



Wood rot under a deck



Debris pile after hard coat stucco removal



Water damage and mold under a deck



Wood sheathing rot behind hard coat stucco under a deck.



Wood rot from an improper kickout flashing.

Examples of common wood rot.



Wood rot under a deck door.



Rotted plywood under the stucco.



Remains of a laminated beam.



Rotted sheathing at a deck



Rotted beam



Rotted wood removal pile